

Bigger Is Better!

***Another Uptime Solution for the rental fleet
Upgrade a Manitex 38s to a 40s and increase rental rates***

Better product, better payback

Included in your Uptime kit: a new Manitex load chart, new LMI Software, and all necessary boom and jib markings.

An extremely painless upgrade which should require minimal time for Installation.

For inquiries about Bulletin 436, contact any Manitex dealer today. For an extensive list of distributors in your area, see our website www.Manitex.com and click on the dealer locator tab.

Or feel free to contact Manitex at 512-942-3031.





Interested in Bulletin 436? Please submit this completed form to the Manitex product support department at 512 942 3094.

Manitex Crane Software Request Form

Dealer	
Requested by	
Purchase Order #	
Phone	

Crane Owner	
Street Address	
City & State	
Phone	
Contact	

Date _____
Crane Model _____
Crane Serial # _____
LMI Type/Model _____
Load Chart Part # _____